Samrudhi Ground Water Consultant

#46, Gamgamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore - 03.

Ref. :..... *Date* :.....09/Aug/2020

REPORT ON GROUND WATER INVESTIGATION

Name BBMP Yelahanka old town

Address Shivanahalli

Location Anjaneya Temple

Topography Normal

Soil Type Black

Rock Type Normal

AE-1

As Asst. Executive Engineer
Yelahanka Sub. Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

AE

Depth 1000 ft

Casing 60

Yield 2 1/2"

Aquifers —

Remarks Acid

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ...

Smt. Kavitha Singh

Water Diviner

Samrudhi Ground Water Consultant

#46, Gamgamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore - 03.

Ref. :.....

Date :.....09/Aug/2020

REPORT ON GROUND WATER INVESTIGATION

Name BBMP Yelahanka old town

Address Yelahanka

Location Vinayaka nagar 1st Cross

Topography Normal

Soil Type 1200 ft

Rock Type Normal

Depth 1200 ft

Casing 80

Yield 2"

Aqufers —

Remarks Nil

AE-1

Asst. Executive Engineer
Yelahanka Sub Divison
(BBMP Pvt. Zn)
Yelahanka, Bangalore

AE

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ...

Smt. Kavitha Singh

Water Diviner

Samrudhi Ground Water Consultant

#46, Gamgamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore - 03.

Ref. :.....

Date :.....09/Aug/2020

REPORT ON GROUND WATER INVESTIGATION

Name BBMP Yelahanka old town

Address Maruthi nagar

Location Suptheogiri Layout 5th cross, Rt side

Topography Normal

Soil Type Black

Rock Type Normal

A6-1

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Depth 1100 ft

Casing 182

Yield 2"

Aqufers —

Remarks Nil

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ...

Smt. Kavitha Singh

Water Diviner

Samrudhi Ground Water Consultant

#46, Gamgamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore - 03.

Ref. :.....

Date :..09/Aug/2020

REPORT ON GROUND WATER INVESTIGATION

Name BBMP Yelahanka Old town

Address Maruthi Nagar

Location 1st Main 4th Cross

Topography Normal

Soil Type Black

Rock Type Normal

AE-1
Asst. Executive Engineer
Yelahanka Sub Divison
(BBMP Link. Zn)
Yelahanka, Bangalore

Depth 1000ft

Casing 140

Yield 2 1/2"

Aqufers —

Remarks Nil

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ...

Smt. Kavitha Singh

Water Diviner